

Mounting diagram for VARISIL type HE option NO surge arresters

Parts supplied

- ① Surge arrester element (x1)
- ② HM12-35 screw (x2)
- ③ WZ12 spring washer (x2)
- ④ Line terminal clamp (x1)
- ⑤ M12 flat washer (x1)

